

	Year Constructed	Material	Length	Width	Area	Square Yards	Lane Miles	Composite Rating	Last Mill/Overlay/construction	2022	2023	2024	2025	2026	Re-evaluate Road Conditions	2027	2028	2029	2030	2031	Re-evaluate Road Conditions	2032	2033	2034	2035	2036	
																Assess for Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	Mill and Overlay	
Brodie	1990	HMAC	3850	48	184,800	20,533	3.645833333	59.5/TBD	2025	Crack Seal	Crack Seal	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	
Clarmac	1999	HMAC	300	48	14,400	1,600	0.284090909	67, TBD	2023	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Curley Mesquite	2000	HMAC	250	18	4,500	500	0.09469697	80	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal	
ERW South	1998	JRCP	2650	48	127,200	14,133	2.509469697	63, TBD	2025	Evaluation and Planning	Evaluation and Planning	Concrete Repairs	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking	Pavement Marking
ERW North	1998	HMAC	1000	48	48,000	5,333	0.946969697	76.5/TBD	2024	Crack Seal	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal	
Home Depot BLVD	2001	JRCP	1962	40	78,480	8,720	1.486363636	66.5	NA	Evaluation and Planning	Delayed	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold	On Hold
Jones	1994	HMAC	3626	30	108,780	12,087	2.060227273	70.0/TBD	2024	Crack Seal	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal
Lone Oak Trail	1998	HMAC	3674	20	73,480	8,164	1.391666667	60.5, TBD	2023	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Lovegrass Lane	2000	HMAC	3938	18	70,884	7,876	1.491666667	86.5	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal and Level Up	Crack Seal										
MSG. Bob Horigan	1996	HMAC	1492	41	61,172	6,797	1.13030303	80	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Pillow Road	1996	HMAC	3018	22	66,396	7,377	1.143181818	70	2012/2013	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal								
Oakdale	2008	HMAC	3235	20	64,700	7,189	1.225378788	86.5	2019	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Reese	2008	HMAC	2526	18	45,468	5,052	0.956818182	73.5	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Sunflower Trail	2006	HMAC	2104	22	46,288	5,143	0.796969697	73.5	NA	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	Crack Seal and Pavement Marking	Crack Seal	
Sunset Trail	1999	HMAC	2019	21	42,399	4,711	0.764772727	67, TBD	2023	Assess for Mill and Overlay	Mill and Overlay	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal
Yellowtail Cove	2000	HMAC	1797	18	32,346	3,594	0.680681818	80	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal and Level Up	Crack Seal										
City Facilities	2018	HMAC			0			83.5	NA	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	Crack Seal	

Capital Expense
Capital Expense
Operations and Maintenance
Operations and Maintenance

Capital Expense
Capital Expense
Operations and Maintenance
Operations and Maintenance